DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 09/18/2013 FORM APPROVED OMB NO. 0938-0391

	IT OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIE IDENTIFICATION NU		1	IPLE CONSTRUCTION IG 01 - Main Building 01	(X3) DATE SI COMPLE	
		505322	•	B. WING		09/1	B/ 2013
NAME OF F	PROVIDER OR SUPPLIER		STREET AD	DRESS, CITY,	STATE, ZIP CODE		
MANOR	CARE HEALTH SE	RVICES-SPO	1	H 6025 AS: ANE, WA			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCE Y MUST BE PRECEDED B' LSC IDENTIFYING INFORM	Y FULL	ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY	N SHOULD BE E APPROPRIATE	(X5) COMPLETION DATE
K 000	INITIAL COMMEN	TS		K 000			
	and Life Safety Reat Manor Care Heat Washington. The I was conducted on 0930 to 1330 by a Washington State I Marshal. During the	esult of an unannoun- certification Survey of lith Services of Spok Fire and Life Safety S 9/18/13 between the representative of the Patrol, Office of the S is Survey I was acco	conducted ane Survey hours of State Fire empanied				
	Assistant who witned during the Survey. 2000 Life Safety Cowith CFR 483.70.	tenance Director and essed any deficiency The existing section ode was used in acco Manor Care is a one	noted of the ordance story				
	grade and is proted Sprinkler System a Alarm System (resi smoke detectors).	Construction with exted by a Type 13 Fin and Automatic/Manua dent rooms do not he This Survey was core Health Survey Tear	e Il Fire ave nducted in				
	Residential Care. It residents with a cur Care has also been	ial and Health Servic Manor Care is license rent census of 91. In In issued a Continuing K147 the use of Mul	ed for 125 Manor Waiver				
		lexible Cords that is	good until				
		neet the Life Safety (opted by CMS based during this Survey.					
	The Surveyor was: Deputy State Fire N Nursing Home Surv 20225 The Surveyor was f Washington State F	reyor rom;					
LABORATO		DERVSOPPLIER REPRESE	ENTATIVE'S SIG	GNATURE	/ TITLE /	· · · · · · · · · · · · · · · · · · ·	(X6) DATE
		LOU			Hamingros	v 9,	126/13
Any deficier other safeg	ncy statement ending with uards provide sufficient p	n an asterisk (*) denotes a rotection to the patients.	a deficiency w (See instruction	hich the institutions.) Except f	ution may be excused from correct for nursing homes, the findings stat	ing providing it is det led above are disclos	ermined that able 90 days

(X2) MULTIPLE CONSTRUCTION

If continuation sheet Page 1 of 5

following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued

program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 09/18/2013 FORM APPROVED OMB NO. 0938-0391

	T OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIE IDENTIFICATION NUM			PLE CONSTRUCTION G 01 - MAIN BUILDING 01	(X3) DATE SURVEY COMPLETED		
		505322		B. WING		09/18/2013		
NAME OF P	ROVIDER OR SUPPLIER	***************************************	STREET AD	DRESS, CITY,	STATE, ZIP CODE			
MANOR CARE HEALTH SERVICES-SPO NORTH				TH 6025 ASSEMBLY (ANE, WA 99205				
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCI Y MUST BE PRECEDED BY LSC IDENTIFYING INFORM	Y FULL	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPR DEFICIENCY)	JLD BE COMPLETION	N	
K 000 K 018 SS=E	Office of the State I Fire Prevention Bur PO Box 19130 Spokane WA. 9921 Telephone: (509) 22 Fax: (509) 227-663 DBFM NFPA 101 LIFE SA	Fire Marshal eau 9-9130 27-6567	her than	K 000	The doors in quel were adjusted	Stron 10/8/13	5	
	hazardous areas are those constructed of wood, or capable of minutes. Doors in a required to resist the notimpediment to the are provided with a the door closed. Do are permitted.	e substantial doors, of 1% inch solid-bond fresisting fire for at I sprinklered buildings to passage of smoke the closing of the door means suitable for futch doors meeting 10.3.6.3 brohibited by CMS recilities.	such as led core east 20 are only . There is rs. Doors reeping 19.3.6.3.6		The doors in quel were adjusted to close & latch proper close & latch proper close & latching. Maintenance Di or duignee will regular rounds unsure all close & latch. Administrator or duignee will to close & latch. Administrator or duignee will to random aucuts unsure doors	ended to		
	Based upon observ Survey conducted of of 0930 to 1330 wh	ot met as evidenced rations made during to on 9/18/13 between to ile accompanied by the following doors no	the the hours facility		closing & latching. to be addressed the safety come	T22 MO		

Printed: 09/18/2013 FORM APPROVED

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-0391 (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING 01 - MAIN BUILDING 01 COMPLETED 505322 B. WING 09/18/2013 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER MANOR CARE HEALTH SERVICES-SPO **NORTH 6025 ASSEMBLY** SPOKANE, WA 99205 (X5) COMPLETION SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) or designer to ensure (CCF)
correction. Daven progressed for #1
1/11/13 K 018 Continued From page 2 K 018 and latching as required: 1. Break Room Door missing latch mechanism (Staff indicated they had a new door on order) Room #122 Close and Latch Room #119 Close and Latch. 4. Double Doors to Lounge Close and Latch Doors are to be properly maintained and adjusted to close and latch to prevent the possible movement of fire or smoke which could place the residents, staff or visitors at risk of possible harm. · All areas indutified K 025 NFPA 101 LIFE SAFETY CODE STANDARD K 025 SS=E Smoke barriers are constructed to provide at

least a one half hour fire resistance rating in accordance with 8.3. Smoke barriers may terminate at an atrium wall. Windows are protected by fire-rated glazing or by wired glass panels and steel frames. A minimum of two separate compartments are provided on each floor. Dampers are not required in duct penetrations of smoke barriers in fully ducted heating, ventilating, and air conditioning systems. 19.3.7.3, 19.3.7.5, 19.1.6.3, 19.1.6.4

This Standard is not met as evidenced by: Based upon observations made during the Survey conducted on 9/18/13 between the hours of 0930 to 1330 while accompanied by facility staff we observed the following areas with penetrations in the walls:

- Fire/Smoke barrier by Medical Records Office (Corridor Wall and Barrier above Fire/Smoke Doors)
- 2. Storage Room in Physical & Occupational

with penetration to the barriers will be repaired.

All potential areas for penetration with were inspected with no issue no issui Maintenance Director
will conduct complete
inspection of all area
after repaire is empleted.
Administrator or designer
will ensure repairs
are emplete.

Maintenance Director

Printed: 09/18/2013 FORM APPROVED

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-0391 (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING 01 - MAIN BUILDING 01 COMPLETED 505322 B. WING 09/18/2013 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE MANOR CARE HEALTH SERVICES-SPO NORTH 6025 ASSEMBLY SPOKANE, WA 99205 SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PROVIDER'S PLAN OF CORRECTION (X5) COMPLETION (EACH DEFICIENCY MUST BE PRECEDED BY FULL **PREFIX** PREFIX (EACH CORRECTIVE ACTION SHOULD BE DATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE TAG DEFICIENCY) is jusponsible to maure correction. K 025 Continued From page 3 K 025 Therapy has penetration in wall that opens to therapy area 3. Fire/Smoke barrier by room #100 (above doors) 4. Fire/Smoke barrier by room #201 (above doors) Fire/Smoke barriers are to be properly maintained to prevent the possible movement of fire or smoke that could place residents, staff or visitors at risk of possible harm.

K 147

with NFPA 70, National Electrical Code. 9.1.2 This Standard is not met as evidenced by: Based upon observations made during the

Electrical wiring and equipment is in accordance

K 147 NFPA 101 LIFE SAFETY CODE STANDARD

Survey conducted on 9/18/13 between the hours of 0930 to 1330 while accompanied by facility staff we observed that the facility is still using multi-plug power strips with flexible cords for non-computer items. Facility was cited for this deficiency last year and requested and was granted a continuing waiver for this deficiency that is good until August 1, 2015.

- Internet Cafe (TV)
- 2. Room #114 (TV)

SS=E

- 3. Room #127 (TV)
- 4. Room #129 (TV)
- 5. Room #127, both sides (TV)
- 6. Room #124 (TV)
- 7. Room #122 (TV)
- 8. Lounge (TV)
- 9. Room #107, both sides

CMS has made an interpretation that multi-plug

a waiver was granted to the facility through 8/1/15 allowing the facility to use approved power strips.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 09/18/2013 FORM APPROVED OMB NO. 0938-0391

. Bar or oomeonom	505322	B. WING	09/18/2013
FEMENT OF DEFICIENCIES PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01	(X3) DATE SURVEY COMPLETED

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

MODILI 6025 ASSEMBLY

	MANOR	CARE HEALTH SERVICES-SPO	NORTH 6025 ASSEMBLY SPOKANE, WA 99205					
Wa	(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY REGULATORY OR LSC IDENTIFYING INFORM	/ FULL	ID PREFIX TAG	PROVIDER'S PLAN OF C (EACH CORRECTIVE ACTI CROSS-REFERENCED TO THE DEFICIENCY	ON SHOULD BE HE APPROPRIATE	(X5) COMPLETION DATE	
	K 147	Continued From page 4 power strips with flexible cords are not a for use with non-computer equipment, o electrical items are to be plugged direct approved electrical outlet or approved c adaptor. Also observed a piggybacked strip in the Ancillary Office (under desk)	other ly into an ube style power	K 147				
			g taku digipalik	i de la companya de l La companya de la companya de	en e			
		2567/02 00\ Provious Versions Obsolete		<u> </u>	JCJE21	If continuation s	heet Page 5 o	